





Gebrauchsanweisung
58 7100
(de,en,fr,nl,it,es,pt)



- 1) 18 7197
V01, V02
42 4755
V03
- 2) 18 7195
V01, V02
42 4767
V03
- 3) 18 7198
V01, V02
42 4757
V03

Conj. transformación:
G30 28 mbar
41 6319
G20 20 mbar
18 7638